CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

OLD BUSINESS

CASE NO: CE03070354 REQUEST FOR EXTENSION

3101 SW 12 PL CASE ADDR:

OWNER: JONES-MURRAY, BERBETH & MURRAY, GLENN INSPECTOR: THOMAS CLEMENTS

VIOLATIONS: NFPA 1 6-1.2

THE EXIT LIGHTS ARE IMPROPERLY WIRED.

NFPA 101 26.3.3.1

THERE IS NO FIRE ALARM SYSTEM PROVIDED.

NFPA 101 7.9.1.1

EMERGENCY LIGHTING IS NOT PROVIDED.

NFPA 101 26.2.3

THE MIMINUM CLEAR WIDTH OF DOOR OPENING INTO BATHROOM IS NOT

PROVIDED.

NFPA 101 26.3.5.2

AN AUTOMATIC FIRE SPRINKLER SYSTEM IS NOT PROVIDED.

NFPA 1 13-1.1

A RANGE HOOD SYSTEM CONSISTENT WITH NFPA 96 IS NOT PROVIDED.

CASE NO: CE02091636 CASE ADDR: 2889 SW 16 ST OWNER: LEWIS, D R & INEZ C

INSPECTOR: WAYNE STRAWN

VIOLATIONS: FBC 104.1

THE BUILDING HAS BEEN ALTERED IN CONFIGURATION AND USE WITHOUT OBTAINING PERMITS. THE ALTERATIONS INCLUDE, BUT MAY NOT BE LIMITED TO THE CONVERSION OF THE BUILDING TO USE AS A ROOMING HOUSE, INTERIOR PARTITIONS CONSTRUCTED, WINDOW UNIT CHANGE-OUTS, A REAR PATIO ROOF CONSTRUCTED AND STAIRWELL GUARDRAILS AND HANDRAILS INSTALLED AND SUBSEQUENTLY REPAIRED

FBC 104.2.11

AIR CONDITIONING UNITS HAVE BEEN INSTALLED MORE THAN 10 FEET ABOVE GRADE WITHOUT OBTAINING PERMITS AND SPECIFICATIONS FOR PROPER AND SAFE ATTACHMENT TO THE BUILDING.

FBC 106.1

THE BUILDING HAS BEEN CONVERTED FROM USE AS A SINGLE FAMILY BUILDING TO USE AS A ROOMING HOUSE AFTER 1955 WITHOUT OB-TAINING THE REQUIRED CERTIFICATE OF OCCUPANCY. THE BUILDING HAS NOT BEEN APPROVED FOR USE AS A ROOMING HOUSE BY BROWARD COUNTY BUILDING DEPARTMENT.

9-238

THIS SECTION IS INCLUDED FOR INFORMATIONAL PURPOSES. PLEASE TAKE SPECIAL NOTE THAT THE ORDINANCE STATES "ROOMING HOUSE SHALL CONFORM TO THE REQUIREMENTS OF THIS ARTICLE REGARDLESS --AND IRRESPECTIVE OF WHEN SUWCH STRUCTURE OR BUILDING MAY

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004 10:00 AM

HAVE BEEN CONSTRUCTED, ALTERED OR REPAIRED".

9-277(e)

THE SECOND FLOOR BEDROOMS DO NOT HAVE THE REQUIRED SEVEN FEET IN CEILING HEIGHT. THE ROOMS VARY IN CEILING HEIGHT FROM 6' 4" TO 6' 7".

FBC 1707.4.2.1

THE WINDOWS INSTALLED ON THE SECOND FLOOR DO NOT BEAR THE REQUIRED LABELS IDENTIFYING THEM AS PASSING THE APPROVAL PROCESS WHICH WOULD DEMONSTRATE COMPLIANCE WITH REQUIRED SPECIFICATIONS.

FBC 1007.6.3

THE INTERIOR STAIRWAY PROVIDING EGRESS FROM THE SECOND FLOOR IS LESS THAN 32" WIDE. THE REQUIREMENT IS 44" ACCORDING TO THE TABLE AT 1004.

FBC 1608.2.1.2

THE HANDRAIL WHICH HAS BEEN INSTALLED DOES NOT PROVIDE THE REQUIRED STRENGTH.

FBC 1608.2.2.3

THE BALUSTRADE OF THE GUARDRAIL SYSTEM AROUND THE STAIRWELL HAS BEEN CRUDELY REPAIRED WITH SMALL ANGLE BRACKETS AND SPLICE PLATES NOT PROVIDING THE STRENGTH REQUIRED BY THE CODE.

FBC 2301.3.1

THE REAR PATIO ROOF STRUCTURE WHICH WAS BUILT WITHOUT PERMITS DOES NOT MEET THE DESIGN REQUIREMENTS OF THE CODE TO ASSURE RESISTANCE TO THE GRAVITY LOAD AND UPLIFT REQUIRE-MENTS. THE MAIN SUPPORT MEMBER AND THE RAFTERS ATTACHED SPAN A LARGE AREA WITH ONLY TWO SUPPORTING AND ANCHORING COLUMNS.

FBC 1015.1

THE ROOF OF THE REAR PATIO DOES NOT HAVE THE REQUIRED GUARDRAIL. THE REAR DOOR OF THE SECOND FLOOR OPENS DIRECTLY ONTO THE PATIO ROOF.

REQUEST FOR EXTENSION

CASE NO: CE03022088

CASE ADDR: 3623 DAVIE BLVD GLASTON, H & MINERVA L

OWNER: INSPECTOR: WAYNE STRAWN

VIOLATIONS: 47-25.3 A.3.d.iv.

THE REQUIRED PHYSICAL BARRIER FOR THE PURPOSE OF A BUFFER BETWEEN RESIDENTIAL AND COMMERCIAL PROPERTIES HAS NOT BEEN PROVIDED.

FBC 104.1

THE FOLLOWING WORK HAS BEEN DONE WITHOUT OBTAINING THE RE-QUIRED PERMITS; ROOF RAFTERS ON THE NORTHEAST CORNER OF THE ROOF AT 3623 HAVE BEEN REPAIRED, A SHORT WALL CONSTRUCTED ON THE EAST END OF THE BUILDING DESIGNED TO PREVENT ACCESS TO THE ALLEY BETWEEN BUILDINGS AND AN AWNING STRUCTURE ATTACHED

AGENDA

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004 10:00 AM

TO THE REAR OF 3623.

FBC 104.2.11

VENTILATION WORK HAS BEEN DONE WITHOUT OBTAINING THE REQUIRED PERMITS. THE WORK INCLUDES, BUT MAY NOT BE LIMITED TO A FAN INSTALLED AT THE REAR OF 3625 (GATOR TINT) AND AN AIR CONDITIONING UNIT INSTALLED AT THE REAR OF 3623.

FBC 104.2.4

PLUMBING WORK HAS BEEN DONE WITHOUT OBTAINING THE REQUIRED PERMITS. THE WORK INCLUDES, BUT MAY NOT BE LIMITED TO: WASTE PIPING ON THE REAR EXTERIOR WALL OF 3635 WHICH DRAINS OUT ON THE GROUND, AND NEW SUPPLY PIPING ON THE REAR WALL OF 3625 (GATOR TINT).

FBC 104.2.5

CIRCUITS HAVE BEEN ADDED TO THE EXISTING BUILDINGS ELECTRICAL SYSTEM WITHOUT OBTAINING THE REQUIRED PERMITS. THE WORK INCLUDES, BUT MAY NOT BE LIMITED TO A CIRCUIT FOR A FAN AT THE REAR OF 3635 AND A CIRCUIT FOR AN OUTSIDE LIGHT AT THE REAR OF 3635.

FBC 3401.6

THE BUILDING IS NOT BEING MAINTAINED IN A SAFE CONDITION BY REASON OF WORK DONE WITHOUT PERMITS. THE WORK INCLUDES, BUT MAY NOT BE LIMITED TO: IMPROPER ROOF REPAIRS AND UNSAFE AWNING STRUCTURE (REAR) AT 3623 AND A SHORT WALL CONNECTING THIS BUILDING TO THE ADJOINING BUILDING ON THE EAST.

CASE NO: CE03050407 CASE ADDR: 1052 NW 53 ST

OWNER: RLM LP & RLM MANAGEMENT LLC

INSPECTOR: WAYNE STRAWN

VIOLATIONS: FBC 104.2.5

CIRCUITS HAVE BEEN ADDED WITHOUT OBTAINING PERMITS. THE ALTERATIONS INCLUDE, BUT MAY NOT BE LIMITED TO, CIRCUITS FOR A WALK IN FREEZER, ADDED WALL OUTLETS AND CIRCUITS TO POWER VEHICLE-BORNE FREEZERS WHILE THEY ARE IN THE BUILDING.

FBC 104.2.11

AN AIR CONDITIONING UNIT AND A WALK-IN FREEZER HAVE BEEN INSTALLED WITHOUT OBTAINING THE REQUIRED PERMITS.

FBC 104.1

A ROLL UP OVERHEAD DOOR HAS BEEN INSTALLED WITHOUT OBTAINING THE REQUIRED PERMIT.

FBC, M 401.2

MOTOR VEHICLES ARE ROUTINELY BROUGHT INTO THE BUILDING AS PART OF THE BUSINESS OPERATION. THE BUILDING DOES NOT HAVE THE REQUIRED VENTILATION TO ALLOW VEHICLES INSIDE THE BUILDING AS SPECIFIED BY FBC,M 403.3.

FBC 3401.6

THE BUILDING IS NOT BEING MAINTAINED SAFE BY REASON OF THE ELECTRICAL WORK DONE WITHOUT PERMITS AND THE MOTOR VEHICLES

CITY OF FORT LAUDERDALE

AGENDA

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

INSIDE THE BUILDING WITHOUT THE PROPER VENTILATION.

REQUEST FOR EXTENSION

CASE NO: CE03101792 CASE ADDR: 2200 MARINA BAY DR E NEW RIVER DRY DOCK INC OWNER:

WAYNE STRAWN INSPECTOR:

VIOLATIONS: NFPA 1 3-5.2

THE FIRE DEPARTMENT ACCESS ROAD IS NOT OF SUFFICIENT WIDTH.

ROADWAY IS 12 FEET WHERE 20 FEET IS REQUIRED.

THE FIRE DEPARTMENT ACCESS ROAD DOES NOT PROVIDE A SUITABLE TURNAROUND AT THE DEAD END. 36 FEET IS PROVIDED WHERE 100

FEET IS REQUIRED.

NFPA 1 3-5.3

THE BRIDGE TO THE PROPERTY IS NOT SUFFICIENT TO ACCOMMODATE FIRE DEPARTMENT VEHICLES, BOTH IN WIDTH AND WEIGHT.

NFPA 1 3-5.4

THE FIRE DEPARTMENT ACCESS ROAD IS NOT PROPERLY IDENTIFIED AS A FIRE LANE.

NFPA 1 3-7.1

THE PREMISES ARE NOT PROPERLY IDENTIFIED WITH THE STREET NUMBERS.

NFPA 10 4-4.1

THE FIRE EXTINGUISHERS THAT ARE PROVIDED ARE DUE FOR ANNUAL CERTIFICATION.

NFPA 303 4-10

A PHONE THAT DOES NOT REQUIRE THE USE OF A COIN IS REQUIRED FOR EMERGENCY NOTIFICATION PURPOSES AND IS REQUIRED TO BE AVAILABLE AT ALL TIMES.IT IS NOT PROVIDED.

NFPA 303 4-3.2.1

FIRE EXTINGUISHERS ARE NOT PROVIDED AS REQUIRED.

FBC 104.1

THE FOLLOWING CONSTRUCTION/IMPROVEMENTS TO THE PROPERTY HAVE BEEN DONE WITHOUT OBTAINING THE REQUIRED PERMITS.

- 1. ALL THE DOCKS AND FLOATING DOCKS AT THE MARINA WITH THE ASSOCIATED PILINGS.
- 2. A LARGE MEMBRANE STRUCTURE ERECTED TO PROVIDE COVER OVER THE DRY DOCK.
- 3. ALTERATIONS TO THE PRINCIPLE BUILDING INCLUDING THE ENCLOSURE OF A PORTION OF THE BUILDING AND THE ELIMINATION OF DOORS AND WINDOWS.
- 4. PERMIT #00101778 AND #99041645 FOR PILING AND DOCKS HAVE EXPIRED WITHOUT PASSING INSPECTIONS AND THEREFORE ARE NOT VALID. THE WORK DONE UNDER THE AUSPICES OF THESE PERMITS NOW EXIST AS WORK WITHOUT PERMITS.

FBC 104.2.4

A WATER SUPPLY SYSTEM HAS BEEN PROVIDED FOR THE MARINA AND FOR THE ADJACENT CONSTRUCTION TRAILERS WITHOUT OBTAINING PERMITS.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004 10:00 AM

FBC 104.2.5

AN ELECTRICAL SYSTEM HAS BEEN INVENTED TO PROVIDE POWER TO THE DOCKS, FLOATING DOCKS, DRY DOCK AND MARINA.

15-28

THE NEW RIVER DRY DOCK AND MARINA IS IN OPERATION WITHOUT OBTAINING A CITY OCCUPATIONAL LICENSE. THE YACHT SALES BUSINESS LOCATED ON THE HOUSE BOAT IS OPERATING WITHOUT A CITY OCCUPATIONAL LICENSE.

47-22.9

SIGNS HAVE BEEN ERECTED/INSTALLED WITHOUT OBTAINING THE REQUIRED PERMITS. THE SIGNS INCLUDE BUSINESS IDENTIFICATION SIGNS AND A FREE STANDING DOCKING FACILITY SIGN FACING THE WATERWAY.

47-24.1 B.

THE MARINA HAS BEEN DEVELOPED WITHOUT OBTAINING A DEVELOPMENT PERMIT FROM THE CITY OF FORT LAUDERDALE.

BCA FFPC F-20.3

A FIRE LINE IS NOT PROVIDED FOR ANY OF THE DOCKS AT THE MARINA.

FBC 602.1

THE FACILITY IS NOT SUPPLIED WITH POTABLE WATER AS REQUIRED. THE FACILITY IS NOT CONNECTED TO THE MUNICIPAL WATER SUPPLY.

FBC 701.2

THE FACILITY IS NOT CONNECTED TO THE MUNICIPAL SEWAGE SYSTEM AS REQUIRED.

NEC 110.12

THE WORK IS NOT DONE IN A NEAT AND WORKMANLIKE MANNER.

NEC 312.2

ATTACHEMENTS (RECEPTACLES) MOUNTED ON PANEL BOARDS MAY CAUSE WATER (MOISTURE) TO ENTER.

NEC 400.10

IN THE ELECTRIC ROOM: CORDS LEAVING ELECTRIC PANEL ARE WIRED INCORRECTLY. ENTIRE ELECTRIC ROOM IS UNSAFE AND UNMAINTAINED.

NEC 400.3

CORDS ARE BEING USED IN PLACES WHERE THEY ARE SUBJECT TO PHYSICAL DAMAGE.

NEC 400.8

EXTENSION CORDS THROUGHOUT THE PROPERTY ARE BEING USED IN PLACE OF FIXED WIRING. I.E. FOR FEEDERS TO PANEL DISTRIBUTION LOCATIONS.

NEC 555.10

ELECTRICAL EQUIPMENT THROUGHOUT THE MARINA IS NOT MOUNTED ON A SUBSTANTIAL SURFACE AS REQUIRED.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

NFPA 303 4-4.2

THE STORAGE BUILDING DOES NOT HAVE THE REQUIRED AUTOMATIC SPRINKLER SYSTEM.

NFPA 303 4-5.1

A FIRE STANDPIPE SYSTEM IS NOT PROVIDED.

NFPA 303 4-6

NO HYDRANTS OR PRIVATE WATER SUPPLY SYSTEM IS PROVIDED FOR FIRE PROTECTION.

NFPA 303 5-1.3

ELECTRICAL LIGHTING IS NOT PROVIDED FOR THE EXTERIOR AREAS, PIERS AND FLOATING DOCKS.

NFPA 303 6-6.4

THE PORTABLE ELECTRIC LAMPS USED IN THE PAINT BOOTH AREA, ARE NOT EXPLOSION PROOF FIXTURES.

NFPA 303 6-6.6

THE INDOOR SPRAY PAINTING OPERATION UNDER THE MEMBRANE STRUCTURE DOES NOT HAVE A FIRE SUPPRESSION SYSTEM THAT COMPLIES WITH NFPA 33.

NFPA 312 2-13

THE REQUIRED FIRE BRIGADE IS NOT PROVIDED.

NFPA 33 4-2.2

THE ELECTRICAL EQUIPMENT IN THE DRY DOCK SPRAY AREA IS NOT LISTED FOR EXPOSURE OF COMBUSIBLE RESIDUE.

SEC 8-146.

THE YACHT SALES BUSINESS LOCATED ON THE HOUSE BOAT DOES NOT HAVE CITY COMMISSION APPROVAL AS REQUIRED.

HEARING COMPUTER SCHEDULED

CASE NO: CE03080101 CASE ADDR: 3701 DAVIE BLVD DUVAL, JOY INSPECTOR: WAYNE STRAWN

VIOLATIONS: 47-20.2.A.

NO OFF STREET PARKING HAS BEEN PROVIDED. THE EMPLOYEES AND CUSTOMERS UTILIZE THE PUBLIC RIGHT OF WAY.

47-22.9

BUSINESS IDENTIFICATION SIGNS HAVE BEEN APPLIED TO THE WINDOWS OF THE BUILDING AND THE COPY OF A FREE STANDING SIGN HAS BEEN CHANGED WITHOUT OBTAINING THE REQUIRED PERMITS.

47-24.1 B.

THE PROPERTY HAS BEEN DEVELOPED FOR BUSINESS USE WITHOUT OBTAINING A DEVELOPMENT PERMIT.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004 10:00 AM

47-25.3.A.3.d.iv.

THE REQUIRED PHYSICAL BARRIER FOR THE PURPOSE OF A BUFFER WALL BETWEEN RESIDENTIAL AND COMMERCIAL PROPERTIES HAS NOT BEEN PROVIDED.

FBC 104.1

THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING PERMITS. THE ALTERATIONS INCLUDE THE FOLLOWING:

- A. THE BUILDING HAS BEEN CHANGED IN USE FROM A RESIDENCE TO A BUSINESS.
- B. AN ADDITION HAS BEEN CONSTRUCTED ON THE NORTH SIDE OF THE BUILDING EXPANDING THE FLOOR AREA OF THE BUILDING AND ALTERING IT'S FOOTPRINT.
- C. A LARGE SECTION OF NORTH EXTERIOR WALL HAS BEEN REMOVED TO ALLOW ACCESS TO THE ADDITION AND ANOTHER SUPPORT SYSTEM CONSTRUCTED TO SUPPORT THE ROOF LOAD.

FBC 104.2.11

NO PERMITS HAVE BEEN OBTAINED FOR THE AIR CONDITIONERS INSTALLED IN THE WALLS OF THE BUILDING.

FBC 104.2.5

ALTERATIONS OF THE ELECTRICAL SYSTEM HAVE BEEN DONE WITHOUT OBTAINING PERMITS. THE WORK INCLUDES CIRCUITRY CONNECTED TO THE CONVERSION OF THE BUILDING, EXTERIOR FLOODLIGHTS AND CIRCUITS FOR THE MANY ROOM AIR CONDITIONERS INSTALLED.

FBC 106.1

THE BUILDING HAS BEEN CHANGED IN "OCCUPANCY" WITHOUT OBTAINING A CERTIFICATE OF OCCUPANCY. THE BUILDING WAS BUILT AS A RESIDENCE BUT IS NOW BEING USED AS A BUSINESS.

FBC 3401.6

THE BUILDING HAS BEEN COMPROMISED DUE TO WORK WITHOUT PERMITS. THE ALTERATION OF A LOAD BEARING WALL AND OF THE ELECTRICAL SYSTEM OF THE BUILDING PRESENT AN UNACCEPTABLE HAZARD.

CASE NO: CE03082092 CASE ADDR: 201 SW 24 ST

OWNER: CRAIG, MARY J TR, HOLLINS, SUSAN L

INSPECTOR: WAYNE STRAWN

VIOLATIONS: FBC 104.1

SHED AND CANOPY STRUCTURES HAVE BEEN ERECTED ON THE NORTH-WEST CORNER OF THE PROPERTY AND A FREESTANDING SIGN ON THE SOUTHEAST CORNER. NO PERMITS WERE ISSUED FOR THE ERECTION/CONSTRUCTION.

FBC 104.2.5

CIRCUITS HAVE BEEN INSTALLED TO PROVIDE POWER TO THE SHED ON THE NORTHWEST CORNER OF THE PROPERTY WITHOUT OBTAINING THE REOUIRED PERMITS.

FBC 3401.6

THE SHED ON THE NORTHEAST CORNER OF THE PROPERTY HAS BEEN ERECTED UNDERNEATH THE FLORIDA POWER AND LIGHT SERVICE DROP.

CITY OF FORT LAUDERDALE

CODE ENFORCEMENT BOARD

CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

AGENDA

10:00 AM

THE CONDUCTORS DO NOT HAVE THE REQUIRED CLEARANCE.

47-22.9

THE SIGN ERECTED ON THE SOUTHEAST CORNER OF THE PROPERTY HAS BEEN ERECTED WITHOUT OBTAINING A PERMIT AS REQUIRED.

OLD BUSINESS

CASE NO: CE03092396 CASE ADDR: 449 NW 15 AVE

ST JOHN UNITED METHODIST

INSPECTOR: DALLAS SHUMAKER

VIOLATIONS: NFPA 1 1-9.4.1

THERE IS A SINGLE-FAMILY RESIDENCE BEING USED AS OFFICE

SPACE WITHOUT A CHANGE OF USE PERMIT.

HEARING COMPUTER SCHEDULED

CASE NO: CE02010716 CASE ADDR: 534 NW 22 AV OWNER: GOLDBERG, ANDREW INSPECTOR: DALLAS SHUMAKER

VIOLATIONS: NFPA 1 1-10.1

SMOKE DETECTORS ARE NOT FUNCTIONING DUE TO LOW BATTERY.

(CHIRPING)

NFPA 1 1-4.5

THERE IS STORAGE IN THE METER ROOM.

NFPA 1 7-6.1.3

THERE IS NO EXTINGUISHER PROVIDED.

CASE NO: CE02110101 CASE ADDR: 1223 NW 6 ST

WRIGHT, DENNIS & WRIGHT, DARNNIE

INSPECTOR: DALLAS SHUMAKER

VIOLATIONS: NFPA 1 1-4.4

UNABLE TO GAIN ENTRY TO CONDUCT ANNUAL FIRE INSPECTION.

CASE NO: CE03091758 CASE ADDR: 519 NW 23 AV
OWNER: BIRCH, DAVID JR INSPECTOR: DALLAS SHUMAKER

VIOLATIONS: NFPA 101 29.3.4.1

THIS BUILDING IS NOT PROTECTED BY AN APPROVED FIRE ALARM

SYSTEM.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

CASE NO: CE03100737 CASE ADDR: 1460 NW 23 AVE

OWNER: PARENTE,GUIDO & JOSEPHINE INSPECTOR: DALLAS SHUMAKER

VIOLATIONS: NFPA 1 1-4.5

THERE ARE MISSING BLANKS IN THE BREAKER BOX ON SOUTH WALL IN WOODWORKING SHOP. ADDITIONALLY, THERE IS A MISSING JUNCTION BOX COVERPLATE ON CEILING OVER NON-PERMITTED OFFICE IN WOOD-

WORKING SHOP.

FBC 104.1

THERE HAS BEEN AN OFFICE STRUCTURE BUILT WITHOUT PERMITS IN

THE WOODWORKING SHOP.

NFPA 1 17-3.2.1

THERE ARE FINISHES BEING SPRAYED OUTSIDE OF THE APPROVED

SPRAY BOOTH.

CASE NO: CE03121616 CASE ADDR: 812 NW 1 ST
OWNER: NATIONSTORAGE R E I T I

INSPECTOR: DALLAS SHUMAKER

VIOLATIONS: NFPA 10 1-6.6

THE FIRE EXTINGUISHERS ARE NOT MOUNTED WITHIN THE LIMITS OF NO HIGHER THAN FIVE FEET AND NO LOWER THAN FOUR INCHES FROM

FLOOR WITH NO GREATER THAN SEVENTY FIVE FEET OF TRAVEL

DISTANCE.

NFPA 10 4-4.1

THERE IS NO SERVICE TAG PRESENT ON THE EXTINGUISHERS.

NFPA 101 42.2.4.1

THE SECOND MEANS OF EGRESS FROM THE VEHICLE STORAGE AREA HAS

BEEN COVERED OVER BY STORAGE PREVENTING ITS USE.

NFPA 101 7.2.1.2.1

THE EXIT DOOR EGRESS WIDTH OUT OF THE FRONT OFFICE RECEPTION

AREA IS LESS THAN THE REQUIRED 90 DEGREE CLEAR WIDTH.

OLD BUSINESS

CASE NO: CE03011765 REQUEST FOR EXTENSION

CASE ADDR: 909 BREAKERS AV

INTERNATIONAL BEACH HOTEL DEVELOPMENT, INC

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 3401.6

THE STEEL SHEET RETAINING WALL ON THE SOUTH SIDE OF

PROPERTY IS DETERIORATING AND RUSTED.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

CASE NO: CE03051896

REQUEST FOR EXTENSION

CASE ADDR: 5470 NW 10 TER
OWNER: DENMAN LIMITED

OWNER: DENMAN LIMITED L L C INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.2.4

NEW AIR CONDITIONING ADDED IN OFFICE ROOMS BUILT WITHOUT FIRST OBTAINING REQUIRED PERMITS.

FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS, THIS INCLUDES:

- 1. ADDED STAIRS AND LOFT IN THE WAREHOUSE
- 2. NEW ROOMS ADDED (COMPLETE NEW DOORS, WINDOWS, ELECTRICAL, AIR CONDITIONING) TO THE EXISTING OFFICE NORTH AND WEST SIDE OF WAREHOUSE
- 3. REPLACE ROLLING SHUTTER DOOR IN THE WEST SIDE OF WAREHOUSE
- 4. BUILT WOOD SHEETING WALL INSIDE OF END WALL ON THE EAST SIDE
- 5. ADDED NEW EXTERIOR DOOR ON THE WEST SIDE OF BUILDING

FBC 104.2.5

ELECTRICAL WORK IN OFFICE ROOM (NEW FIXTURES, NEW PANEL, ETC) WAREHOUSE WITHOUT FIRST OBTAINING REQUIRED PERMITS.

FBC 11-4.1.2(5)(a)

THERE IS NO HANDICAP PARKING.

FBC 11-4.6.4

THERE IS NO HANDICAP SIGNAGE.

47-20.20 H.

PARKING LOT IS IN DISREPAIR AND NEEDS REPAIR AND RESTRIPING.

9-306

EXTERIOR BUILDING NEEDS PAINTING.

9-305

LANDSCAPING NEEDS MAINTENANCE.

FBC 11-4.3

THERE IS NO ACCESSIBLE ROUTE (RAMP) FROM PARKING LOT TO BUILDING.

FBC 3401.6

THE FOLLOWING ITEMS REQUIRE MAINTENANCE:

- 1. EXIT LIGHTS NOT WORKING
- 2. EXTERIOR MULTIRIB PANELS ARE DAMAGE/RUSTED ALMOST ON ALL EXTERIOR WALLS NEED STRUCTURAL REPAIRS.
- 3. OVERHANG STEEL BEAM ON THE SOUTH SIDE OVER DOCK IS RUSTED NEEDS IMMEDIATE REPAIR.

REQUEST FOR ABATEMENT

AGENDA

CODE ENFORCEMENT BOARD

CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

- 4. STEEL BEAMS ATTACHED TO THE EAST END WALL ARE RUSTED AND STRUCTURALLY DAMAGED NEED IMMEDIATE REPAIR.
- 5. STEEL BEAM ON THE SOUTHWEST CORNER IS RUSTED AND IN NEED OF IMMEDIATE REPAIR.
- 6. STEEL COLUMNS AND THEIR ATTACHMENT BOLTS TO THE FLOOR IS RUSTED AND NEEDS REPAIR
- 7. DOCK STEM WALL DAMAGED ON THE WEST SIDE, NEEDS REPAIRS
- 8. EXHAUST FANS NOT WORKING
- 9. ELECTRICAL PANEL AND GUTTER MISSING COVER, WIRES HANGING, UNSAFE CONDITION, NEED COMPLETE CHECK-UP AND A LETTER FROM AN ENGINEER ABOUT ITS SAFETY
- 10. ELECTRICAL LIGHTS NOT WORKING IN OFFICE AND WAREHOUSE

CASE NO: CE03061868
CASE ADDR: 3200 N OCEAN BLVD # 1607

OWNER: BROWN, GARY D
INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMIT. THIS INCLUDES, BUT IS NOT LIMITED TO:

- 1. INSTALLED NEW DRYWALL CEILINGS
- 2. INSTALLED NEW DOOR

FBC 104.2.5

NEW ELECTRICAL WORK, WITHOUT FIRST OBTAINING REQUIRED PERMITS.

HEARING COMPUTER SCHEDULED

CASE NO: CE00051788 CASE ADDR: 3115 NE 25 ST

OWNER: BRODER, EDWARD & PATRICIA

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: 47-34.1 A.1.

BUILT A GARAGE WITHIN THE SIDE YARD AND REAR YARD SETBACKS, IN VIOLATION OF THE PERMITTED DIMENSIONAL REQUIREMENTS AS DETAILED IN TABLE 47-5.31.

FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENT TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED PERMITS. THESE INCLUDE:

1. BUILT A GARAGE IN THE SIDE YARD AND REAR YARD SETBACKS.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

CASE NO: CE03012254

CASE ADDR: 4545 N FEDERAL HWY

OWNER: ATLANTIC SHORES HEALTHCAR INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PER-

MITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

1. INSTALLED FENCE AND DUMPSTER ENCLOSURE.

CASE NO: CE03071409 CASE ADDR: 5921 NE 14 WY OWNER: NEMETH, ANGELINA INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PER-

MITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

1. INSTALLED FENCE

2. GARAGE DOOR BOARDED UP

CASE NO: CE03071744 CASE ADDR: 2920 SW 4 AV OWNER: CAL ASSOCIATES INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 11-4.6.1

THE REQUIRED HANDICAP PARKING FOR THE EXISTING BUILDING IS

NOT IN COMPLIANCE WITH CODE.

FBC 11-4.6.4

THE REQUIRED HANDICAP SIGNAGE FOR THE EXISTING BUILDING IS

NOT IN COMPLIANCE WITH CODE.

15 - 28

ENGAGING IN BUSINESS WITHOUT FIRST OBTAINING AN OCCUPATIONAL

LICENSE.

Sec. 47-20.8.

PARKING LOT NEEDS RESTRIPING.

CASE NO: CE03080357

CASE ADDR: 4040 GALT OCEAN DR
OWNER: OCEAN MANOR CONDO ASSN

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE

BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PER-

MIT. THIS INCLUDES:

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004 10:00 AM

1. REMOVED/REPLACED KITCHEN CABINETS.

FBC 104.2.4

PLUMBING WORK IN KITCHEN WITHOUT OBTAINING REQUIRED PERMIT.

FBC 104.2.5

ELECTRICAL WORK WITHOUT FIRST OBTAINING REQUIRED PERMITS.

CE03080656 CASE NO: CASE ADDR: 1221 NE 1 AV KIRKLAND, SYNDLE INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING

PERMIT. THIS INCLUDES:

1. DEMOLITION WORK

- 2. NEW/REPLACE WINDOWS
- 3. NEW/REPLACE DOORS
- 4. NEW/REPLACE KITCHEN CABINETS

FBC 104.2.4

PLUMBING WORK IN KITCHEN WITHOUT FIRST OBTAINING REQUIRED PERMITS.

FBC 104.2.5

ELECTRICAL WORK WITHOUT FIRST OBTAINING REQUIRED PERMITS.

CASE NO: CE03082117 CASE ADDR:

611 NE 13 ST 611 NE 13 STREET LLC OWNER:

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: 15-28

ENGAGING IN BUSINESS WITHOUT FIRST OBTAINING AN OCCUPATIONAL

LICENSE.

FBC 11-4.6.1

THE REQUIRED HANDICAP PARKING FOR THE EXISTING BUILDING IS

NOT IN COMPLIANCE WITH CODE.

FBC 11-4.6.4

THE REQUIRED HANDICAP SIGNAGE FOR THE EXISTING BUILDING IS

NOT IN COMPLIANCE WITH CODE.

FBC 11-4.7

THE REQUIRED HANDICAP RAMP FOR THE EXISTING BUILDING IS NOT

IN COMPLIANCE WITH CODE.

FBC 104.2.11

INSTALLED/REPLACED AIR CONDITIONING UNIT WITHOUT FIRST

OBTAINING REQUIRED PERMITS.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

CASE NO: CE03102068

CASE ADDR: 3208 BAYVIEW DR # 101

OWNER: WAY, WILSON E INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.9.3.1

PERMIT #02061403 ISSUED ON 6/20/02 HAS BEEN EXPIRED AND

VOIDED WITHOUT FINAL INSPECTIONS.

CASE NO: CE03111504
CASE ADDR: 3057 CENTER AV

OWNER: MAVRIS, JULIA NICOLAOU

INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE BUILDING WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES:

- 1. INSTALLED NEW PAVERS
- 2. DEMO OF WALL ON THE EXTERIOR OF BUILDING
- 3. REMOVE AND REPLACE WINDOWS
- 4. NEW SOFFIT AND FASCIA BEING INSTALLED OVER EXISTING
- 5. NEW WINDOW AIR CONDITIONING UNIT INSTALLED

FBC 104.2.5

NEW ELECTRICAL WORK IN PROGRESS WITHOUT FIRST OBTAINING REQUIRED PERMITS.

FBC 104.2.4

NEW WINDOW AIR CONDITIONER INSTALLED WITHOUT FIRST OBTAINING REOUIRED PERMITS.

CASE NO: CE03111716
CASE ADDR: 1544 NE 4 AV
OWNER: CHERISOL, BERNARD
INSPECTOR: MOHAMMED MALIK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS ON THE PROPERTY WITHOUT FIRST OBTAINING THE REQUIRED BUILDING

PERMIT. THIS INCLUDES:

1. INSTALLED RADIO ANTENNA

FBC 104.2.5

ELECTRICAL WORK ON THE ANTENNA WITHOUT FIRST OBTAINING REQUIRED PERMITS.

REQUEST FOR EXTENSION

REQUEST FOR EXTENSION

AGENDA

CODE ENFORCEMENT BOARD

CITY COMMISSION MEETING ROOM - CITY HALL

JANUARY 27, 2004 10:00 AM

OLD BUSINESS

CASE NO: CE02060922

CASE ADDR: 632 SW 4 AVE OWNER: FELL, JAMES R & LILLIAN C INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

THE REAR APARTMENT OF THIS DUPLEX HAS BEEN CONVERTED INTO AN OFFICE WITHOUT FIRST OBTAINING A BUILDING PERMIT. A PERMIT WAS ISSUED IN 1987 TO CONVERT THE FRONT APARTMENT TO A LAW OFFICE, BUT THE REAR APARTMENT WAS NOT INCLUDED IN THIS

PERMIT.

FBC 11-4.1.2(5)(a)

THERE IS NO HANDICAP PARKING AT THIS OFFICE BUILDING.

FBC 106.1

THE REAR OFFICE OF THIS BUILDING IS BEING OCCUPIED AS AN OFFICE WITHOUT FIRST OBTAINING A CERTIFICATE OF OCCUPANCY FROM THE BUILDING OFFICIAL.

15-28

THE AUDIO VIDEO INTELLIGENCE BUSINESS IS OPERATING AT THIS LOCATION IWTHOUT AN OCCUPATIONAL LICENSE.

CASE NO: CE02070641

CASE ADDR: 1604 SW 5 CT

POLK, WILLIAM F & HELI BONN OWNER:

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

ADDED A KITCHEN UPSTAIRS, A LOWER BATHROOM AND ENCLOSED THE REAR PORCH WITHOUT FIRST OBTAINING A BUILDING PERMIT.

FBC 104.2.4

ADDED PLUMBING TO THE UPPER KITCHEN AND LOWER BATHROOM WITHOUT FIRST OBTAINING A PLUMBING PERMIT.

FBC 104.2.5

ADDED ELECTRIC TO THE ENCLOSED REAR PORCH, THE UPPER KITCHEN AND LOWER BATHROOM WITHOUT FIRST OBTAINING A PLUMBING PERMIT

CASE NO: CE03020870 CASE ADDR: 1340 SW 35 AV

LOUIE, CORRINA Y TR & RIEWE, STEPHEN M TR

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

THE FOLLOWING WORK WAS DONE WITHOUT FIRST OBTAINING A BUILDING PERMIT:

- 1. CUT THE TIE BEAM AND REPLACED A DOOR AT THE SOUTH SIDE OF THE CENTER BREEZEWAY.
- 2. APARTMENT A4 HAS BEEN ILLEGALLY CONVERTED INTO TWO (2) LIVING UNITS (A4 & A4A).
- 3. THE FRONT AND REAR WALLS HAVE BEEN OPENED TO ACCOM-

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004 10:00 AM

MODATE WALL AIR CONDITIONING UNITS IN APARTMENTS A4 AND A4A.

FBC 104.2.4

PLUMBING LINES HAVE BEEN ADDED TO THE REAR EXTERIOR WALL AND THE EXTERIOR WALL OF THE CENTER BREEZEWAY WITHOUT FIRST OBTAINING A PLUMBING PERMIT.

FBC 104.2.5

ELECTRICAL LINES HAVE BEEN ADDED TO THE REAR EXTERIOR WALL, THE EXTERIOR WALL OF THE CENTER BREEZEWAY AND TO THE WALL AIR CONDITIONING UNITS IN APARTMENT A4 AND A4A WITHOUT FIRST OBTAINING AN ELECTRICAL PERMIT.

FBC 104.2.11

WALL AIR CONDITIONING UNITS HAVE BEEN ADDED TO APARTMENTS A4 AND A4A WITHOUT FIRST OBTAINING A MECHANICAL PERMIT.

9-279(f)

A PLUMBING WASTE LINE DISCHARGES TO THE GROUND AT THE REAR EXTERIOR WALL, JUST NORTH OF THE CENTER BREEZEWAY.

9-280(f)

THERE IS A MISSING ROOF DRAIN PIPE AT THE NORTH END OF THE REAR WALL OF THE BUILDING, WHICH SHOULD BE REPLACED.

9-280(h)(1)

THE POOL WOOD AND CHAIN LINK FENCES ARE DAMAGED AND ARE NOT BEING MAINTAINED.

9-280 (b)

THE RAIN GUTTERS ARE RUSTED AND DAMAGED. THERE ARE MISSING WINDOW SCREENS THROUGHOUT THE BUILDING. THE DOOR, DOOR FRAME AND WALL ARE ROTTED AT THE STORAGE AREA UNDER THE NORTH STAIRWAY.

9 - 304 (b)

THE PARKING LOT HAS POTHOLES AND IS NOT BEING MAINTAINED TO THE MINIMUM STANDARDS OF THIS CODE.

FBC 3401.6

THERE ARE STORED ITEMS IN THE METER ROOM. THIS IS NOT SAFE AND IS NOT ALLOWED.

9-305(b)

THERE IS MISSING GRASS AT THE SOUTHWEST CORNER OF THE BUILDING.

47-19.4 D.8.

THE DUMPSTER ENCLOSURE FENCE WALLS ARE DAMAGED AND REQUIRE REPAIR.

CODE ENFORCEMENT BOARD

CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

CASE NO: CE03041438 REQUEST FOR EXTENSION

CASE ADDR: 1320 SW 28 ST

OWNER: ALMENDARES, DENNIS A & ALMENDARES, DIANELIS ET AL INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

NEW WINDOWS AND THE FRONT DOOR HAVE BEEN INSTALLED WITHOUT

FIRST OBTAINING A BUILDING PERMIT.

FBC 104.9.3.1

PERMIT 00071418 FOR REROOFING HAS EXPIRED SINCE NO PASSING

INSPECTION WAS OBTAINED IN OVER 90 DAYS.

HEARING COMPUTER SCHEDULED

CASE NO: CE03010203 CASE ADDR: 1425 SW 1 ST OWNER: CHEELEY, MARK O INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.9.3.1

PERMIT 02070884 FOR GLASS BLOCK, FRENCH DOORS, WOOD SIDING,

AND SHUTTERS HAS EXPIRED SINCE NO PASSING INSPECTION HAS

BEEN OBTAINED IN OVER 90 DAYS.

CASE NO: CE03011456 CASE ADDR: 1527 SW 20 AVE

OWNER: ORR, RANDY & LEVINSON, ADAM

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.9.3.1

THE FOLLOWING PERMITS HAVE EXPIRED SINCE NO PASSING INSPECTIONS HAVE BEEN OBTAINED IN OVER 90 DAYS. - 02121366 PAVER DRIVEWAY & REAR CONCRETE PATIO

- 03011156 WOOD FENCE 95 LF

- 02081238 AFTER THE FACT ELECTRICAL - 02081240 AFTER THE FACT PLUMBING - 02081239 AFTER THE FACT MECHANICAL

- 02080888 AFTER THE FACT RENOVATE EXISTING SFR

- 02041906 UPGRADE SPRINKLER SYSTEM

CASE NO: CE03040989

CASE ADDR: 820 W LAS OLAS BLVD

STRICKLIN, EDWARD & STRICKLIN, KAREN

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.9.3.1

PERMIT 02110300 FOR AFTER THE FACT RE-ROOFING HAS EXPIRED SINCE NO PASSING INSPECTION HAS BEEN OBTAINED IN OVER

90 DAYS.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

CASE NO: CE03042054
CASE ADDR: 1111 SW 2 CT
OWNER: SPECTOR, JUSTIN
INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

THE FOLLOWING WORK HAS BEEN DONE WITHOUT FIRST OBTAINING A BUILDING PERMIT:

- A VINYL FENCE HAS BEEN ADDED AT THE WEST SIDE OF THE PROPERTY.
- CONCRETE DRIVEWAYS AND WALKWAYS HAVE BEEN ADDED.
- THE DUMPSTER ENCLOSURE AND THE WATER HEATER SHED HAVE BEEN ADDED.
- THE KITCHEN IN APARTMENT ONE HAS BEEN REMODELED.
- NEW EXTERIOR DOORS AND WINDOWS HAVE BEEN INSTALLED ON ALL UNITS.
- THE REAR BUILDING BATHROOM WINDOWS HAVE BEEN REPLACED WITH GLASS BLOCK.

FBC 104.2.4

THE WATER HEATER HAS BEEN REPLACED AND THE KITCHEN SINK IN APARTMENT ONE REPLACED WITHOUT FIRST OBTAINING A PLUMBING PERMIT.

FBC 104.2.5

NEW ELECTRICAL WIRING HAS BEEN ADDED TO THE WEST WALL OF THE REAR BUILDING AND WIRING TO THE CENTRAL A/C SYSTEM OF APARTMENT ONE AND TWO HAS BEEN DONE WITHOUR FIRST OBTAINING AN ELECTRICAL PERMIT.

FBC 104.2.11

THE CENTRAL A/C SYSTEMS HAVE BEEN REPLACED IN APARTMENT ONE AND TWO WITHOUT FIRST OBTAINING A MECHANICAL PERMIT.

FBC 3401.6

THERE IS AN OPEN PLUMBING WASTE LINE AT THE WEST WALL OF THE REAR BUILDING AND THE FIRE EXTINGUISHER ON THE EXTERIOR WALL IS EXPIRED.

9-281 (b)

THERE IS AN OLD COUCH DISCARDED AND ON THE DRIVEWAY.

CASE NO: CE03052162
CASE ADDR: 409 SW 11 ST
OWNER: KRIGEL, RICHARD
INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.9.3.1

PERMIT 02101216 FOR THE WOOD FENCE HAS EXPIRED SINCE NO PASSING INSPECTION HAS BEEN OBTAINED IN OVER 90 DAYS.

CODE ENFORCEMENT BOARD

CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

CASE NO: CE03062505
CASE ADDR: 1000 SW 17 ST
OWNER: BUTLER, JOE Z
INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

THE KITCHEN HAS BEEN REMODELED AND THE EXTERIOR DOORS REPLACED WITHOUT FIRST OBTAINING A BULDING PERMIT.

FBC 104.2.4

THE KITCHEN AND BATHROOM FIXTURES HAVE BEEN REPLACED

WITHOUT FIRST OBTAINING A PLUMBING PERMIT.

CASE NO: CE03072412 CASE ADDR: 911 SW 30 ST

OWNER: VALENCIA, MONICA 1/2 INT EA, TORADO, DINORA

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

THE WINDOWS AND EXTERIOR DOORS HAVE BEEN REPLACED WITHOUT

FIRST OBTAINING A BUILDING PERMIT.

CASE NO: CE03080742
CASE ADDR: 821 SW 26 ST
OWNER: PRIEST, ANTHONY A
INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

THE EXTERIOR DOORS WERE REPLACED WITHOUT FIRST OBTAINING A

BUILDING PERMIT.

CASE NO: CE03091679
CASE ADDR: 1620 SW 33 AVE
OWNER: FRASER, PATRICIA
INSPECTOR: KENNETH REARDON

VIOLATIONS: 9-305(b)

THE YARD IS NOT BEING MAINTAINED. THERE ARE AREAS OF OVERGROWTH AND OTHER AREAS OF MISSING GROUND COVER.

FBC 104.1

A CONCRETE DRIVEWAY HAS BEEN INSTALLED WITHOUT FIRST OB-

TAINING A BUILDING PERMIT.

CASE NO: CE03092176
CASE ADDR: 901 SW 16 ST
OWNER: BELL, BRIAN M
INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

A SHED HAS BEEN INSTALLED IN THE REAR YARD WITHOUT FIRST

OBTAINING A BUILDING PERMIT.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

CASE NO: CE03092246
CASE ADDR: 836 SW 25 ST
OWNER: WOODRUFF, WAYNE
INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

THE WOOD FENCE WAS INSTALLED WITHOUT FIRST OBTAINING A

BUILDING PERMIT.

47-19.5.D.4.

THIS FENCE IS NOT INSTALLED WITH THE FINISHED SIDES FACING

THE NEIGHBORING PROPERTIES, AS REQUIRED.

CASE NO: CE03092378
CASE ADDR: 2619 SW 2 AVE

OWNER: GENERAL HARDWOODS & MILLWORK

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

PREPARING TO POUR A CONCRETE SLAB WITHOUT FIRST OBTAINING

A BUILDING PERMIT.

CASE NO: CE03101011 CASE ADDR: 1705 SW 11 ST

OWNER: SULLIVAN, DOROTHY PARKER

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

THE CARPORT HAS BEEN ENCLOSED WITHOUT FIRST OBTAINING A

BUILDING PERMIT.

FBC 106.1

THE ENCLOSED CARPORT IS OCCUPIED WITHOUT FIRST OBTAINING A

CERTIFICATE OF OCCUPANCY FROM THE BUILDING OFFICIAL.

CASE NO: CE03101498
CASE ADDR: 3904 SW 12 PL
OWNER: GREENFIELD, JOHN J
INSPECTOR: KENNETH REARDON

VIOLATIONS: 9-305(b)

THE REAR YARD IS OVERGROWN AND THERE IS MISSING GRASS/GROUND

COVER IN THE FRONT YARD.

FBC 104.1

THE WINDOWS AND FRONT DOOR HAVE BEEN REPLACED WITHOUT FIRST

OBTAINING A BUILDING PERMIT.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL

JANUARY 27, 2004 10:00 AM

CASE NO: CE03102094 CASE ADDR: 3308 SW 3 AVE

OWNER: C & S UNLIMITED INC INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.2.11

INSTALLED A CENTRAL AIR CONDITIONING SYSTEM WITHOUT FIRST

OBTAINING A MECHANICAL PERMIT.

FBC 104.2.5

INSTALLED ELECTRICAL WIRING TO THE NEW CENTRAL AIR CONDITIONING SYSTEM WITHOUT FIRST OBTAINING AN ELECTRICAL PER-

МТТ

CASE NO: CE03102254 CASE ADDR: 1903 SW 2 ST

OWNER: NITSCHE, MANFRED & JUTTA

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

SECURITY BARS HAVE BEEN INSTALLED WITHOUT FIRST OBTAINING A

BUILDING PERMIT.

FBC 1005.5

THE WINDOWS ARE THE SECOND MEANS OF ESCAPE FROM THE BEDROOMS

AND THE SECURITY BARS BLOCKING THE WINDOWS DO NOT HAVE

PROPER EMERGENCY RELEASE DEVICES.

CASE NO: CE03110052 CASE ADDR: 2514 SW 09 AV

OWNER: FADGEN, JEROME S & KATHLEEN ANN

INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

SEVERAL WINDOWS HAVE BEEN REPLACED WITHOUT FIRST OBTAINING

A BUILDING PERMIT.

CASE NO: CE03110062
CASE ADDR: 908 SW 18 ST
OWNER: WILSON, BRIAN R
INSPECTOR: KENNETH REARDON

VIOLATIONS: FBC 104.1

A FENCE WAS INSTALLED WITHOUT FIRST OBTAINING A BUILDING

PERMIT.

CASE NO: CE03110112 CASE ADDR: 2636 SW 2 ST

OWNER: INVESTORS LENDING INC

INSPECTOR: KENNETH REARDON

VIOLATIONS: 9-279(f)

THERE IS NO WATER SERVICE TO THIS HOUSE.

AGENDA

CODE ENFORCEMENT BOARD
CITY COMMISSION MEETING ROOM - CITY HALL
JANUARY 27, 2004
10:00 AM

9-305(b)

THERE IS MISSING GRASS IN AREAS.

FBC 104.1

THE FOLLOWING WORK HAS BEEN PERFORMED WITHOUT FIRST OBTAINING A BUILDING PERMIT:

SECURITY BARS ON THE WINDOWS

WOOD FENCE

EXTERIOR DOORS

THE SOUTHEAST BEDROOM WALL ALTERED AT THE WINDOW

THE WEST WALL WINDOWS HAVE BEEN COVERED OVER AND WALLED

UP

FBC 104.2.4

THE WATER HEATER HAS BEEN REPLACED WITHOUT FIRST OBTAINING A PLUMBING PERMIT.

FBC 3401.6

THERE IS EXTENSIVE TERMITE DAMAGE THROUGHOUT THE HOUSE.

OLD BUSINESS

CASE NO: CE01041565 CASE ADDR: 117 NW 3 AV

OWNER: FLAGLER POP II LLC INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: 301(a)

REPLACING ROOF ON WAREHOUSE, INSTALLED NEW WOOD PARTITIONS INSIDE, AND COVERED WITH PLYWOOD, ALL WITHOUT PERMITS.

301.1(e)

INSTALLED ELECTRICAL IN THE NEW WALLS, WITHOUT PERMITS OR

INSPECTIONS.

47-21.9 G.1.

THERE IS NO LANDSCAPING ASSOCIATED WITH THIS BUILDING.

CASE NO: CE02101544

4 REQUEST FOR EXTENSION

CASE ADDR: 2933 POINSETTIA ST

OWNER: GATOR EAST WIND PARTNERS LLLP

INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1

THERE HAVE BEEN IMPROVEMENTS TO THIS PROPERTY THAT HAVE BEEN DONE WITHOUT PERMITS, THAT INCLUDE BUT ARE NOT LIMITED TO:

- (1) BUILT AN IN GROUND FOUNTAIN POOL WITH A BRICK PAVER
 - PATHWAY.
- (2) ENCLOSED ELEVATOR SHAFT.
- (3) ENCLOSED STAIRWAY.
- (4) ADDED A ROOF TOP APARTMENT.

FBC 104.2.11

AGENDA

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

INSTALLED A WALL AIR CONDITIONING UNIT IN THE ROOF TOP APARTMENT WITHOUT A PERMIT.

FBC 104.2.4

ADDED PLUMBING WITHOUT PERMITS THAT INCLUDE BUT ARE NOT

- (1) PLUMBING FOR THE POOL FOUTAIN.
- (2) PLUMBING FOR THE ROOF TOP APARTMENT.

FBC 104.2.5

ADDED ELECTRICAL WITHOUT PERMITS THAT INCLUDE BUT IS NOT LIMITED TO:

- (1) ELECTRICAL FOR THE POOL FOUNTAIN.
- (2) ELECTRICAL FOR THE ROOF APARTMENT.

FBC 1015.1

THERE IS NO GUARDRAIL AROUND THE PERIMETER OF THE ROOF WHERE THE ROOF TOP APARTMENT IS LOCATED.

CASE NO: CE03021409

CASE ADDR: 1045 NE 18 AVE
OWNER: BOEMERMANN, RICHARD J INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: 47-21.1.A.

THE LANDSCAPING AND GRASS IS NOT BEING MAINTAINED PER THE CITY OF FORT LAUDERDALE'S MINIMUM HOUSING CODE OR ULDR.

9-304.(b)

THE PARKING LOTS HAVE NOT BEEN MAINTAINED. THERE ARE HOLES IN THE ASPHALT AND THE PARKING LOTS NEED TO BE REPAINTED AND RESTRIPED.

9-306

THE RAILINGS ON THE TWO STORY BUILDING FROM THE GROUND LEVEL TO THE SECOND FLOOR AND THE RAILINGS ON THE SECOND FLOOR ARE LOOSE AND IN DISREPAIR.

9-307(a)

SEVERAL OF THE JALOUSIE WINDOWS ARE BROKEN AND/OR IN DISREPAIR. THERE ARE SCREENS MISSING FROM SEVERAL WINDOWS.

FBC 104.2.11

INSTALLED WINDOW AIR CONDITIONER UNITS WITHOUT A PERMIT.

FBC 104.2.5

INSTALLED EXTERIOR LIGHTING AND WIRING WITHOUT PERMIT AND NOT PER CODE.

FBC 3401.6

THE BUILDINGS HAVE NOT BEEN MAINTAINED ACCORDING TO THE CITY OF FORT LAUDERDALE MINIMUM HOUSING CODE AND THE FLORIDA BUILDING CODE, INCLUDING, BUT NOT LIMITED TO:

1. THE CEILING IN THE ROOM WITH THE WATER HEATER THAT HAS HOLES IN IT AND PARTS OF THE CEILING HAVE BEEN

AGENDA

CODE ENFORCEMENT BOARD

CITY COMMISSION MEETING ROOM - CITY HALL

JANUARY 27, 2004

10:00 AM

REPLACED AND NOT PER CODE.

2. THERE IS A TOILET IN THE ROOM WITH THE WATER HEATER THAT IS NOT WORKING.

CASE NO: CE03071745

CASE ADDR: 401 N FT LAUD BEACH BLVD OWNER: SABLE RESORTS INC INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1

ALTERED THE STRUCTURE WITHOUT PERMITS AND NOT PER CODE

INCLUDING BUT NOT LIMITED TO :

(1) BUILT AN ACCESSIBLE RAMP

- (2) BUILT A WOODEN RAILING ON THE RAMP
- (3) INSTALLED ACCESSIBLE PARKING SPACES
- (4) INSTALLED ACCESSIBLE SIGNAGE

FBC 104.2.7

INSTALLED A SIGN FOR THE DECK RESTAURANT WITHOUT A PERMIT.

FBC 11-4.6.1

ALL COMMERCIAL BUILDINGS MUST HAVE THE PROPER NUMBER OF ACCESSIBLE PARKING SPACES PER THE CODE.

FBC 11-4.6.4

ALL BUILDINGS THAT HAVE ACCESSIBLE PARKING SPACES MUST HAVE PROPER SIGNAGE.

FBC 11-4.8

ALL BUIDINGS THAT HAVE ACCESSIBLE PARKING SPACES MUST ALSO PROVIDE ACCESSIBLE ENTRY TO THE BUILDING, INCLUDING BUT NOT LIMITED TO AN ACCESSIBLE RAMP.

FBC 3401.6

THE FRONT PIPE AWNING FRAME IN THE FRONT OF THE PROPERTY IS IN DISREPAIR AND RUSTING, COMPROMISING ITS INTEGRITY AND STRENGTH.

FBC 1203.4.2

THERE ARE TEO MISSING EXHAUST FANS IN RESTROOMS OF THIS

CASE NO: CE03080405

REQUEST FOR EXTENSION

CASE ADDR: 445 SE 16 ST

B M C ENTERPRISES LLC OWNER: INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: 9-277(c)(1)

THE ADDITION OF 4 BUNK BEDS PER SLEEPING ROOM EXCEEDS THE MINIMUM SQUARE FEET REQUIREMENT OF THIS CODE.

9-304(b)

ALL MULTI APARTMENT BUILDINGS ABOVE A DUPLEX MUST HAVE A PAVED HARD DUSTLESS SURFACE FOR VEHICLE PARKING.

FBC 104.1

AGENDA

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

SUBDIVIDED ROOMS WITHOUT PERMITS, AND NOT PER CODE.

FBC 104.2.11

INSTALLED WALL AND WINDOW AIR CONDITIONING UNITS WITHOUT PERMITS, AND THE TOILET ROOMS DO NOT HAVE WINDOWS THAT OPEN OR MECHANICAL VENTILATION.

FBC 104.2.4

INSTALLED PLUMBING AND SINKS IN TOILET ROOMS WITHOUT PERMITS.

FBC 104.2.5

INSTALLED ELECTRIC WITHOUT PERMITS AND NOT PER CODE, AND THEY HAVE WIRED THE SMOKE DETECTORS TO LIGHT FIXTURES CIRCUITS THAT HAVE SWITCHES.

FBC 1203.4.2

ALL TOILET ROOMS NEED A WINDOW THAT OPERATES OR A MECHANICAL EXHAUST FAN.

FBC 704.2.2.3

THE ONE HOUR FIRE SEPARATION BETWEEN ADJOINING SLEEPING ROOMS HAS BEEN COMPROMISED BY THE INSTALLATION OF HOLLOW CORE DOORS.

CASE NO: CE03080411 CASE ADDR: 421 SE 16 ST

OWNER: B M C ENTERPRISES LLC INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1

SUBDIVIDED ROOMS WITHOUT PERMITS, AND NOT PER CODE.

FBC 104.2.4

INSTALLED PLUMBING AND SINKS IN TOILET ROOMS WITHOUT PERMITS.

FBC 104.2.5

INSTALLED ELECTRIC WITHOUT PERMITS AND NOT PER CODE AND THEY HAVE WIRED THE SMOKE DETECTORS TO LIGHT FIXTURES CIRCUITS THAT HAVE SWITCHES.

FBC 104.2.11

INSTALLED WALL AND WINDOW AIR CONDITIONING UNITS WITHOUT PERMITS, AND THE TOILET ROOMS DO NOT HAVE WINDOWS THAT OPEN OR MECHANICAL VENTILATION.

FBC 1203.4.2

ALL TOILET ROOMS NEED A WINDOW THAT OPERATES OR A MECHANICAL EXHAUST FAN.

9-304(b)

ALL MULTI APARTMENT BUILDINGS ABOVE A DUPLEX MUST HAVE A PAVED HARD DUSTLESS SURFACE FOR VEHICLE PARKING.

FBC 704.2.2.3

THE ONE HOUR FIRE SEPARATION BETWEEN ADJOINING SLEEPING

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

ROOMS HAS BEEN COMPROMISED BY THE INSTALLATION OF HOLLOW CORE DOORS.

9-277(c)(1)

THE ADDITION OF 4 BUNK BEDS PER SLEEPING ROOM EXCEEDS THE MINIMUM SQUARE FEET REQUIREMENT OF THIS CODE.

CASE NO: CE03080412 REQUEST FOR EXTENSION

CASE ADDR: 420 SE 16 ST

OWNER: B M C ENTERPRISES LLC INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1

SUBDIVIDED ROOMS WITHOUT PERMITS, AND NOT PER CODE.

FBC 104.2.4

INSTALLED PLUMBING AND SINKS IN TOILET ROOMS WITHOUT PERMITS.

FBC 104.2.5

INSTALLED ELECTRIC WITHOUT PERMITS AND NOT PER CODE, AND THEY HAVE WIRED THE SMOKE DETECTORS TO LIGHT FIXTURES CIRCUITS THAT HAVE SWITCHES.

FBC 104.2.11

INSTALLED WALL AND WINDOW AIR CONDITIONING UNITS WITHOUT PERMITS, AND THE TOILET ROOMS DO NOT HAVE WINDOWS THAT OPEN OR MECHANICAL VENTILATION.

FBC 1203.4.2

ALL TOILET ROOMS NEED A WINDOW THAT OPERATES OR A MECHANICAL EXHAUST FAN.

9 - 304 (b)

ALL MULTI APARTMENT BUILDINGS ABOVE A DUPLEX MUST HAVE A PAVED HARD DUSTLESS SURFACE FOR VEHICLE PARKING.

FBC 704.2.2.3

THE ONE HOUR FIRE SEPARATION BETWEEN ADJOINING SLEEPING ROOMS HAS BEEN COMPROMISED BY THE INSTALLATION OF HOLLOW CORE DOORS.

9-277(c)(1)

THE ADDITION OF 4 BUNK BEDS PER SLEEPING ROOM EXCEEDS THE MINIMUM SQUARE FEET REQUIREMENT OF THIS CODE.

REQUEST FOR EXTENSION

CASE NO: CE03080413
CASE ADDR: 416 SE 16 ST
OWNER: B M C ENTERPRISES LLC INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 704.2.2.3

THE ONE HOUR FIRE SEPARATION BETWEEN ADJOINING SLEEPING ROOMS HAS BEEN COMPROMISED BY THE INSTALLATION OF HOLLOW CORE DOORS.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004 10:00 AM

9-277(c)(1)

THE ADDITION OF 4 BUNK BEDS PER SLEEPING ROOM EXCEEDS THE MINIMUM SQUARE FEET REQUIREMENT OF THIS CODE.

FBC 104.1

SUBDIVIDED ROOMS WITHOUT PERMITS, AND NOT PER CODE.

FBC 104.2.4

INSTALLED PLUMBING AND SINKS IN TOILET ROOMS WITHOUT PERMITS.

FBC 104.2.5

INSTALLED ELECTRIC WITHOUT PERMITS AND NOT PER CODE, AND THEY HAVE WIRED THE SMOKE DETECTORS TO LIGHT FIXTURES CIRCUITS THAT HAVE SWITCHES.

FBC 104.2.11

INSTALLED WALL AND WINDOW AIR CONDITIONING UNITS WITHOUT PERMITS, AND THE TOILET ROOMS DO NOT HAVE WINDOWS THAT OPEN OR MECHANICAL VENTILATION.

FBC 1203.4.2

ALL TOILET ROOMS NEED A WINDOW THAT OPERATES OR A MECHANICAL EXHAUST FAN.

9 - 304 (b)

ALL MULTI APARTMENT BUILDINGS ABOVE A DUPLEX MUST HAVE A PAVED HARD DUSTLESS SURFACE FOR VEHICLE PARKING.

HEARING COMPUTER SCHEDULED

CASE NO: CE03021984

CASE ADDR: 3000 E SUNRISE BLVD OWNER: CARLTON TOWER CONDO ASSN

INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1

BUILT A ROOM IN THE PUMP ROOM OF THIS CONDO BUILDING WITHOUT

PERMITS.

FBC 3401.6

THE DOOR LEADING TO THE ROOF IS IN DISREPAIR AND NEEDS

TO BE REPLACED.

CE03030921 CASE NO: CASE ADDR: 2626 DEL MAR PL OWNER: PAOLINO, LOUIS JR INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: 47-19.5 H.2.

INSTALLED A HEDGE BETWEEN TWO PROPERTIES TO THE SEA WALL

EXCEEDING THE 30" ABOVE THE GRADE.

FBC 104.1

INSTALLED A BOAT DAVIT/HOIST & LADDER ON THE REAR CONCRETE

BOAT DOCK WITHOUT PERMIT

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

CASE NO: CE03081895 CASE ADDR: 1629 NE 5 CT

RION, WILLIAM L & RION, DONNA R OWNER:

INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1

INSTALLED BRICKS IN THE SWALE WITHOUT A PERMIT.

CE03100579 CASE NO: CASE ADDR: 1140 NW 19 AV OWNER: HERON, JENNIFER INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1

CONVERTED THE CARPORT TO A ROOM AND INSTALLED KITCHEN

CABINETS WITHOUT PERMITS.

FBC 104.2.4

INSTALLED A SPRINKLER PUMP WITHOUT A PERMIT.

FBC 104.9.3.1

THE AFTER THE FACT ROOF PERMIT #02050482 HAS EXPIRED WITH

NO INSPECTIONS, THUS IS NULL AND VOID.

CASE NO: CE03100620

CASE ADDR: 800 SE 4 ST # 204 REINBOLT, RICHARD OWNER: INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1

THE FOLLOWING CONSTRUCTION/IMPROVEMENTS TO THIS APARTMENT

WERE COMPLETED WITHOUT PERMITS, REMOVED WALLS.

FBC 104.2.4

REMOVED PLUMBING FIXTURES WITHOUT A PERMIT.

FBC 104.2.5

ALTERED THE ELECTRICAL WITHOUT A PERMIT.

CASE NO: CE03100977 CASE ADDR: 112 NE 5 ST

OWNER: SAILBOAT BEND PROPERTIES LLC

INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1

THE FOLLOWING CONSTRUCTION/IMPROVEMENTS TO THIS MULTI UNIT APARTMENT BUILDING HAVE BEEN DONE WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLED

CABINETS, AND WINDOWS.

FBC 104.2.4

INSTALLED SINKS AND WATERHEATERS, TOILETS AND PLUMBING

CODE ENFORCEMENT BOARD
CITY COMMISSION MEETING ROOM - CITY HALL
JANUARY 27, 2004
10:00 AM

10.00

WITHOUT PERMITS.

FBC 104.2.5

INSTALLED ELECTRICAL AND NEW FIXTURES, WITHOUT PERMITS.

FBC 104.2.11

INSTALLED NEW WINDOW AND WALL A.C. UNITS WITHOUT PERMITS.

FBC 3401.6

THE PARKING AREA FOR THIS MULTI UNIT APARTMENT BUILDING

HAS NOT BEEN MAINTAINED PER THE CITY CODE.

CASE NO: CE03101084 CASE ADDR: 921 NE 17 TER

OWNER: PHILLIPS, MARJORIE & HILTON, KARINA ROSS

INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: 9-313(b)

THE HOUSE NUMBERS ARE MISSING.

FBC 104.1

THE FOLLOWING CONSTRUCTION/IMPROVEMENTS TO THIS PROPERTY WERE COMPLETED WITHOUT PERMITS, INSTALLED A WOODEN FENCE,

INSTALLED PAVERS IN THE DRIVE AND SWALE AREAS.

CASE NO: CE03102163

CASE ADDR: 219 S FT LAUD BEACH BLVD # 2 OWNER: SWISS BEACH HOLDINGS INC

INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: 9-313(b)

THE NUMBERS ON THIS NIGHT CLUB BUILDING ARE THE WRONG SIZE

AND CANNOT BE SEEN FROM THE STREET.

FBC 104.2.7

INSTALLED SIGNS AND BANNERS ON THIS BUILDING WITHOUT

PERMITS.

CASE NO: CE03102497 CASE ADDR: 550 BREAKERS AVE

OWNER: BEACH BREEZE RESORT MOTEL INC

INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1

INSTALLED WINDOWS IN THIS BEACH HOTEL BUILDING WITHOUT A

PERMIT.

FBC 104.2.11

INSTALLED WALL A.C. UNITS WITHOUT A PERMIT.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

CASE NO: CE03102506

CASE ADDR: 545 N FT LAUD BEACH BLVD

OWNER: GOLD COAST MERRIMAC BEACH HOTEL INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1

INSTALLED WINDOWS IN THIS BEACH HOTEL WITHOUT A PERMIT.

FBC 104.2.11

INSTALLED WALL A.C. UNITS WITHOUT A PERMIT.

FBC 3401.6

(1) THERE ARE SEVERAL AREAS OF SPALLING CONCRETE ON THIS BUILDING. (2) THE ASPHALT IN THE SWALE AREA HAS A FEW

POT HOLES.

CASE NO: CE03102530
CASE ADDR: 551 N FT LAUD BEACH BLVD
OWNER: MERRIMAC INC

INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1

INSTALLED WINDOWS IN THIS BEACH HOTEL WITHOUT A PERMIT.

FBC 104.2.11

INSTALLED WALL AND WINDOW A.C. UNITS WITHOUT A PERMIT.

FBC 3401.6

THERE ARE SEVERAL AREAS OF SPALDING CONCRETE INCLUDING

THE DRIVE THRU.

CASE NO: CE03102597 CASE ADDR: 544 BREAKERS AV MERRIMAC INC OWNER:

INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.1

INSTALLED WINDOWS IN THIS BUILDING WITHOUT A PERMIT.

FBC 104.2.11

INSTALLED WALL A.C. UNITS WITHOUT A PERMIT.

CE03110911 CASE NO:

CASE ADDR: 529 N FT LAUD BEACH BLVD

LATROBE, RUTH W INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 3401.6

THE DRIVE THRU OVERHANG AT THIS BEACH HOTEL IS NOT BEING MAINTAINED PER THE CITY OF FORT LAUDERDALE CODE, OR THE FLORIDA BUILDING CODE, THE LACK OF PROPER MAINTENANCE CAUSED THE HEAVY EXTERIOR STUCCO TO FALL AND DAMAGE A VEHICLE ON 11/07/2003 PER POLICE REPORT # 03-145614, THE PATCH JOB THAT WAS DONE IS NOT PER CODE, AND IS UNSAFE.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004 10:00 AM

CASE NO: CE03121338

CASE ADDR: 1500 W COMMERCIAL BLVD OWNER: TATA INTERNATIONAL INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.9.3.1

INSTALLED 4 AWNINGS ON THIS TRAVEL LODGE MOTEL WITH PERMIT #98060923 WHICH HAS FAILED FINAL ON 3/29/99, THUS IS NULL

AND VOID.

CASE NO: CE03121910

CASE ADDR: 1706 S FEDERAL HWY
OWNER: WILLIAMSON, ROBERT
INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 104.2.7

RE-INSTALLED 4TH BANNER SIGN IN 2 LOCATIONS ON THIS BUILDING OF THIS MIAMI SUB RESTAURANT WITHOUT A PERMIT, PER CODE BOARD CASE #CE01060446, THIS IS A REPEAT VIOLATION.

CASE NO: CE03121935 CASE ADDR: 2140 NW 6 ST

OWNER: INTERBAY FUNDING LLC INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: 47-21.9 G.1.

THERE IS NO RETROACTIVE VUA LANDSCAPING AT THIS CAR WASH PROPERTY.

47-25.3 A.3.d.

THERE IS NO BUFFERYARD WALL ON THIS COMMERCIAL PROPERTY ABUTTING THE RESIDENTIAL AREA IN THE REAR.

FBC 104.1

ALTERED THIS STRUCTURE TO INCLUDE BUT NOT LIMITED TO; POURED CONCRETE FOR SLABS AT THIS CAR WASH, ALTERED THE INTERIOR OF THIS BUILDING, ALL WITHOUT PERMITS.

FBC 11-4.6.1

THERE ARE NO ACCESSIBLE PARKING SPACES, OR STRIPPING FOR THIS PROPERTY.

FBC 1820.3.

WIRE MESH WAS NOT INCLUDED PRIOR TO THE POURING OF THE CONCRETE SLABS.

FPC 403.1

THERE IS NO SINK IN THE TOILET ROOM OF THIS CAR WASH BUSINESS.

CODE ENFORCEMENT BOARD

CITY COMMISSION MEETING ROOM - CITY HALL

JANUARY 27, 2004 10:00 AM

OLD BUSINESS

CE02062015 CASE NO:

REQUEST FOR EXTENSION

CASE ADDR: 3045 N FEDERAL HWY # 70 OWNER: GREG ALIFERIS HOLDINGS INC INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE INTERIOR OF THE BUILDING AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS IN-CLUDES, BUT IS NOT LIMITED TO:

- A. REMOVAL AND RELOCATION OF BEVERAGE BARS.
- B. DEMOLITION AND REMOVAL OF SOUTHEAST STAGE.
- C. INSTALLATION OF LIGHT VALANCE OVER DANCE FLOOR.
- D. BEVERAGE BARTOPS CHANGED AND RE-CONFIGURED.
- E. DOORWAY PASS-THRU OPENINGS IN EXTERIOR WALL SECTION.
- F. CREATION OF MAIN STAGE AREA AND REMOVAL OF HANDRAILS.
- G. CONSTRUCTION OF STORE ROOM AREA ADDITION.
- CONSTRUCTION OF WEST EXTERIOR WALL AND ENCLOSURE.
- I. CONSTRUCTION OF LOFT STORAGE AREA.
- J. INSTALLATION OF CONCRETE SLABS IN STORAGE AREAS.
- K. INSTALLATION OF WOOD DANCE FLOOR AREA.
- L. INSTALLATION OF SERVICE BEVERAGE BARS.
- M. CONSTRUCTION OF ROOF SECTIONS OVER ORIGINAL PARKING AREA.

FBC 104.2.4

THERE HAVE BEEN RENOVATION, RELOCATION AND NEW INSTALLATION OF PLUMBING AND MECHANICAL RELATED ITEMS WITHOUT FIRST OB-TAINING THE REQUIRED PERMITS. THESE ITEMS INCLUDE, BUT ARE NOT LIMITED TO:

- A. REMOVAL OF PLUMBING CONNECTIONS AND CAPPING OF TIE-IN
- B. INSTALLATION OF ICE MACHINES (3).
- C. INSTALLATION OF COOLER.
- D. RELOCATION OF BEVERAGE BARS.

FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS. THIS WORK INCLUDES, BUT IS NOT LIMITED TO:

- A. INTERIOR SERVICE SUB-PANEL IS BEING USED AS AIR-CONDITIONING DISCONNECT SWITCH.
- B. DANCE FLOOR AND STAGE LIGHTING INSTALLED.
- C. NUMEROUS WIRES AND CORDS EXPOSED AND NOT PROPERLY SECURED.
- D. RELOCATION OF BEVERAGE BAR WIRING AND TERMINATIONS CAPPED.
- E. INTERIOR WALL OUTLETS IN OUTSIDE BAR ADDITION NOT PER PLAN.
- F. EXTERIOR SERVICE DISCONNECT AND BUSS PANEL HAS BEEN CONCEALED BY CONSTRUCTION OF WALL ADDITION.
- G. STAGE OUTLETS RELOCATED.

AGENDA

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

CASE NO: CE03040968

REQUEST FOR EXTENSION

CASE ADDR: 1617 NW 5 AV OWNER: THEOPHILE, GERMAINE INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED

A. INSTALLATION OF CHAIN-LINK FENCING

B. ENCLOSURE AND ADDITION TO EXISTING RESIDENCE

CE03041128

CASE ADDR: 4950 W PROSPECT RD

OWNER: FRYD, ISAAC TR INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

CASE NO:

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE INTERIOR OF THE BUILDING AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS IN-CLUDES, BUT IS NOT LIMITED TO:

- A. INSTALLATION OF OFFICE PARTITIONS
- B. INSTALLATION OF ACOUSTICAL CEILINGS
- C. INSTALLATION OF STOREFRONT BEHIND ROLL-UP DOOR
- D. INSTALLATION OF SOUND STUDIOS
- E. INSTALLATION OF RECEPTION AREA
- F. DEMOLITION OF EXISTING PARTITIONS

FBC 104.2.4

THERE HAVE BEEN RENOVATION, RELOCATION AND NEW INSTALLATION OF PLUMBING ITEMS WITHOUT FIRST OBTAINING THE REQUIRED PER-MITS. THESE ITEMS INCLUDE, BUT ARE NOT LIMITED TO:

A. REMOVAL OF PLUMBING CONNECTIONS AND CAPPING OF TIE-IN LINES.

FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS. THIS WORK INCLUDES, BUT IS NOT LIMITED TO:

- A. INTERIOR SERVICE SUB-PANEL HAS INCORRECT COVER
- STAGE LIGHTING INSTALLED
- C. NUMEROUS WIRES AND CORDS EXPOSED AND NOT PROPERLY SECURED.
- D. WIRING AND TERMINATIONS CAPPED
- E. INTERIOR WALL OUTLETS NOT PER PLAN

FBC 11-4.6.1

ACCESSIBLE PARKING SPACES FOR HANDICAP HAVE NOT BEEN PROVIDED.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004 10:00 AM

FBC 11-4.6.4

THE REQUIRED SIGNAGE FOR HANDICAP ACCESSIBLE PARKING HAS NOT BEEN PROVIDED.

FBC 11-4.7

THE REQUIRED RAMPS FOR HANDICAP ACCESSIBLE PARKING HAVE NOT BEEN PROVIDED.

FBC 1016.3.1

EMERGENCY EXIT SIGNS REQUIRED.

15-28

OCCUPATIONAL LICENSE REQUIRED. BUSINESS IS CURRENTLY OPERATING WITHOUT THE PROPER LICENSES.

FBC 1016.2.1

EMERGENCY LIGHTING REQUIRED.

FBC 704.2.3.1

ONE (1) HOUR FIRE SEPARATION IS REQUIRED BETWEEN TENANTS.

HEARING COMPUTER SCHEDULED

CASE NO: CE03010616 CASE ADDR: 1344 NW 4 AV

OWNER: CABRERA, DANIEL E & RABEN, ROBERT

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

1. CONSTRUCTION OF STORAGE SHED STRUCTURE AT THE REAR OF THE PROPERTY.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

CASE NO: CE03060963 CASE ADDR: 1417 NW 13 PL OWNER: SPATE, GERALD INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF REPLACEMENT WINDOWS B. MODIFICATION OF FRONT PORCH COLUMNS

C. INSTALLATION OF WALL SHEATHING AND WINDOW ENCLOSURES

D. EXTENSION OF FRONT ROOF E. ENCLOSURE OF CARPORT

CASE NO: CE03061111 CASE ADDR: 5149 NW 09 AV
OWNER: LAMAR ELECTRONICS INC

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE INTERIOR OF THE BUILDING AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

- A. INSTALLATION OF DISPLAY WALLS & FIREPLACES B. INSTALLATION OF INTERIOR FRAMING & PARTITIONS
- C. INSTALLATION OF DRYWALL

FBC 104.2.4

THERE HAS BEEN MODIFICATIONS TO THE INTERIOR PLUMBING FIXTURES AND CONNECTIONS WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS. THIS WORK INCLUDES THE CONNECTIONS TO LIGHTING AND OUTLETS.

FBC 104.2.11

INSTALLATION OF AIR CONDITIONING AND VENTILATION WAS MODIFIED WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

CASE NO: CE03071392 CASE ADDR: 1640 NW 9 AV
OWNER: TAYLOR, ANTHONY B INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE

REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL

JANUARY 27, 2004 10:00 AM

A. REMODEL OF INTERIOR/EXTERIOR STRUCTURE, ROOFING AND REPAIR WORK.

CASE NO: CE03071836 CASE ADDR: 1129 NW 7 TER

OWNER: STARNES, RANDY & FITZGERALD, DARRELL

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

- A. INSTALLATION OF NEW DOORS AND REPLACEMENT WINDOWS.
- B. INSTALLATION OF KITCHEN CABINETS.
- C. INSTALLATION OF DRYWALL FINISHES AND TEXTURES.
- D. INSTALLATION OF ROOF.

FBC 104.2.11

INSTALLATION OF NEW AIR CONDITIONING UNIT WAS INSTALLED WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

FBC 104.2.4

THERE HAVE BEEN MODIFICATIONS TO THE INTERIOR PLUMBING FIXTURES AND DRAINLINES WITHOUT FIRST OBTAINING THE RE-OUIRED PERMITS.

FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS. THIS WORK INCLUDES THE CONNECTIONS TO THE NEW A/C UNIT, HOT WATER HEATER AND MAIN SERVICE.

._____

CASE NO: CE03071837
CASE ADDR: 6968 NW 30 AV
OWNER: CARROLL, JOAN N
INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

TIMITED IO:

A. INSTALLATION OF WOOD PORCH ENCLOSURE

B. INSTALLATION OF WOOD FENCE

CASE NO: CE03072352
CASE ADDR: 346 CITY VIEW DR
OWNER: SIEGFRIED, ARTHUR L
INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIM-

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

ITED TO:

A. INSTALLATION OF REPLACEMENT DOORS (FRENCH TYPE)

CASE NO: CE03072354

329 CITY VIEW DR FREEMAN, THOMAS R CASE ADDR: OWNER: INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIM-

ITED TO:

A. INSTALLATION OF REPLACEMENT DOORS (FRENCH TYPE)

CASE NO: CE03072355 CASE ADDR: 6795 NW 17 AV
OWNER: SIVORE, GEORGE A JR & SIVORE, MARY C

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

FBC 104.2.11

INSTALLATION OF AIR CONDITIONING AND VENTILATION WAS MODIFIED WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

FBC 104.2.4

THERE HAS BEEN MODIFICATIONS TO THE INTERIOR PLUMBING FIXTURES AND CONNECTIONS WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WIHTOUT FIRST OBTAINING REQUIRED PERMITS. THIS WORK INCLUDES THE CONNECTIONS TO LIGHTING, SERVICE PANELS AND OUTLETS.

CASE NO: CE03080472 CASE ADDR: 1032 NW 4 AV

OWNER: ALEXIS, GARRY & ALEXIDOR, JEAN EDDY

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF REPLACEMENT WINDOWS.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

CASE NO: CE03081668
CASE ADDR: 740 NW 20 AV
OWNER: HART, ETORE C
INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 3401.6

FAILURE TO MAINTAIN PROPERTY. DETERIORATION OF EXTERIOR ROOFING, DECKING AND FACIA HAS CAUSED NUMEROUS LEAKES TO THE INTERIOR OF THE STRUCTURE CAUSING DAMAGE TO STRUCTURAL

ELEMENTS.

CASE NO: CE03081681
CASE ADDR: 824 NW 15 AV
OWNER: VALADE,RYAN
INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIM-

ITED TO:

A. INSTALLATION OF REPLACEMENT DOOR AND FRAME.

CASE NO: CE03090082 CASE ADDR: 1205 NW 1 AV

OWNER: LOPEZ, ISRAEL J & MILKA

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

A. INSTALLATION OF KITCHEN CABINETS
B. INSTALLATION OF REPLACEMENT DOORS

FBC 104.2.11

INSTALLATION OF NEW CENTRAL AIR CONDITION UNIT WAS INSTALLED WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

CASE NO: CE03090083 CASE ADDR: 1209 NW 1 AV

OWNER: LOPEZ,ISRAEL & MILKA INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

A. INSTALLATION OR SECURITY BARS

B. INSTALLATION OF REPLACEMENT DOORS

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

CASE NO: CE03090085 CASE ADDR: 1213 NW 01 AV OWNER: LOPEZ, ISREAL INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF SECURITY BARS

CE03091165 CASE NO: CASE ADDR: 1345 NW 7 TER BACIGALUPPI, PHILIP INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE INTERIOR OF THE BUILDING AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS IN-CLUDES, BUT IS NOT LIMITED TO:

- A. ENCLOSURE OF CARPORT
- B. INSTALLATION OF DOORS AND WINDOWS

FBC 104.2.11

INSTALLATION OF WALL AIR-CONDITIONING UNIT WAS INSTALLED WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

FBC 104.2.4

THERE HAS BEEN MODIFICATIONS TO THE PLUMBING AND DRAIN LINES WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS.

CE03091528 CASE NO: CASE ADDR: 934 NW 4 AV OWNER: PIERRE, MARIE INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

A. INSTALLATION OF WOOD FENCING

B. INSTALLATION OF REPLACEMENT WINDOWS C. INSTALLATION OF REPLACEMENT DOORS

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

CASE NO: CE03091604 CASE ADDR: 735 NW 14 WY OWNER: DUCTANT, JOE D
INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF REPLACEMENT DOORS B. INSTALLATION OF REPLACEMENT WINDOWS

C. INSTALLATION OF CONCRETE BLOCK AND STUCCO

D. INSTALLATION OF INTERIOR CABINETS

CASE NO: CE03091730
CASE ADDR: 210 NW 17 CT
OWNER: DOWNS, WILLIAM JAME

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIM-ITED TO:

A. INSTALLATION OF FENCING

B. INSTALLATION & REPLACEMENT OF ROOFING (SHINGLES)

FBC 104.2.1

INSTALLATION OF AN EXTERIOR WALK-IN COOLER & REFRIGERATION SYSTEM WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

FBC 104.2.5

INSTALLATION OF ELECTRICAL CONNECTIONS AND EQUIPMENT FOR REFRIGERATION SYSTEMS WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

CASE NO: CE03091963 CASE ADDR: 6721 NW 22 TER

OWNER: LARUE, BRIAN A & LARUE, JEANNINE M

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

A. INSTALLATION OF PAVER DRIVEWAY AND WALKWAY AREA.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

CASE NO: CE03092303 CASE ADDR: 742 NW 15 WY OWNER: MY OWNINGS LLC INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF DRYWALL TO CEILING

B. INSTALLATION OF ROOFING

C. INSTALLATION OF WOOD STORAGE SHED

CE03100429 CASE NO: CASE ADDR: 1612 NW 10 AV OWNER: KELTGEN, JOAN E INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAININ THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF REPLACEMENT DOORS B. INSTALLATION OF REPLACEMENT WINDOWS C. INSTALLATION OF KITCHEN CABINETS

CASE NO: CE03100539 CASE ADDR: 827 NW 10 TER

OWNER: RICHARDS, CHARLES & LEONIE & KING, LEROY INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE INTERIOR OF THE BUILDING AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS IN-CLUDES, BUT IS NOT LIMITED TO:

A. INSTALLATION OF KITCHEN CABINETS B. INSTALLATION OF WALL SURFACES

FBC 104.2.4

THERE HAS BEEN MODIFICATIONS TO THE INTERIOR PLUMBING CON-NECTIONS AND FIXTURES AND THE INSTALLATION OF NEW WATER HEATER WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS. THIS WORK INCLUDES THE CONNECTIONS AND OUTLETS FOR NEW KITCHENS.

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

CASE NO: CE03100540 CASE ADDR: 829 NW 10 TER

OWNER: RICHARDS, CHARLES & LEONIE & KING, LEROY INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE INTERIOR OF THE BUILDING AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS IN-CLUDES, BUT IS NOT LIMITED TO:

- A. INSTALLATION OF KITCHEN CABINETS B. INSTALLATION OF WALL SURFACES
- FBC 104.2.4

THERE HAS BEEN MODIFICATIONS TO THE INTERIOR PLUMBING CON-NECTIONS AND FIXTURES AND THE INSTALLATION OF NEW WATER HEATER WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS. THIS WORK INCLUDES THE CONNECTIONS AND OUTLETS FOR NEW KITCHENS.

CASE NO: CE03100541 CASE ADDR: 833 NW 10 TER

RICHARDS, CHARLES & LEONIE & KING, LEROY

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE INTERIOR OF THE BUILDING AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS IN-CLUDES, BUT IS NOT LIMITED:

- A. INSTALLATION OF KITCHEN CABINETS
- B. INSTALLATION OF WALL SURFACES

FBC 104.2.4

THERE HAS BEEN MODIFICATIONSN TO THE INTERIOR PLUMBING CONNECTIONS AND FIXTURES AND THE INSTALLATION OF NEW WATER HEATER WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS. THIS WORK INCLUDES THE CONNECTIONS AND OUTLETS FOR NEW KITCHENS.

CE03100542 CASE NO: CASE ADDR: 837 NW 10 TER

RICHARDS, CHARLES & LEONIE & KING, LEROY

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

INTERIOR OF THE BUILDING AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS IN-CLUDES, BUT IS NOT LIMITED TO:

- A. INSTALLATION OF KITCHEN CABINETS
- B. INSTALLATION OF WALL SURFACES

FBC 104.2.4

THERE HAS BEEN MODIFICATIONS TO THE INTERIOR PLUMBING CONNECTIONS AND FIXTURES AND THE INSTALLATION OF NEW WATER HEATER WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS. THIS WORK INCLUDES THE CONNECTIONS AND OUTLETS FOR NEW KITCHENS.

CASE NO: CE03100708
CASE ADDR: 6191 NW 32 WY
OWNER: WOOLSTENCROFT, LAURA L SMITH

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

A. ENCLOSURE OF ROOM STRUCTURE WITH WINDOW AND WALL SECTIONS.

CASE NO: CE03100824 CASE ADDR:

545 NW 07 TER BI-ADS INC & WESTSIDE GAZETTE OWNER:

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 11-4.6.1

ACCESSIBLE PARKING SPACES FOR HANDICAP HAVE NOT BEEN PROVIDED.

FBC 11-4.6.4

THE REQUIRED SIGNAGE FOR HANDICAP ACCESSIBLE PARKING HAS NOT BEEN PROVIDED.

FBC 11-4.7

THE REQUIRED RAMPS FOR HANDICAP ACCESSIBLE PARKING HAVE NOT BEEN PROVIDED.

FBC 3401.6

FAILURE TO MAINTAIN THE PROPERTY. THIS INCLUDES BUT NOT LIMITED TO:

- 1. DAMAGE TO FENCE
- 2. DAMAGE TO PROPERTY WALL
- 3. ASPHALT PARKING AREAS NEED REPAIRS
- 4. UNPROTECTED LIGHT FIXTURES
- 5. LOOSE AND EXPOSED WIRING

CODE ENFORCEMENT BOARD

CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

- 6. LOFT AREA HAS NO HAND OR GUARDRAILS
- 7. NUMEROUS OPENINGS IN EXTERIOR WALLS

FBC 104.1

THERE HAVE BEEN IMPROVEMENTS AND/OR MODIFICATIONS MADE TO THE INTERIOR STRUCTURE WITHOUT OBTAINING THE REQUIRED PERMITS. THIS WORK INCLUDES BUT NOT LIMITED TO:

- 1. INSTALLATION OF OFFICE
- 2. INSTALLATION OF DOORS AND WINDOWS
- 3. INSTALLATION OF WINDOW SECTION IN OFFICE WALL

FBC 104.2.5

THERE HAS BEEN ELECTRICAL CONNECTIONS AND WORK DONE WITHOUT THE REQUIRED PERMITS INCLUDING THE LIGHT FIXTURES AND A/C UNIT.

FBC 104.2.4

THERE HAS BEEN PLUMBING CONNECTIONS AND WORK DONE WITHOUT THE REQUIRED PERMITS INCLUDING REPLACEMENT OF FIXTURES.

FBC 104.2.11

THERE HAS BEEN MECHANICAL WORK DONE WITHOUT THE REQUIRED PERMITS INCLUDING THE INSTALLATION OF NEW A/C UNIT.

FBC 1016.2.1

EMERGENCY LIGHTING AND EXIT SIGNAGE REQUIRED.

FBC 1016.3.1

EMERGENCY LIGHTING AND EXIT SIGNAGE REQUIRED.

47-21.8.A.

THE OWNER, TENANT AND AGENT ARE JOINTLY RESPONSIBLE FOR THE MAINTENANCE OF LANDSCAPING AND IRRIGATION.

9-281 (b)

MINIMUM STANDARDS FOR EXTERIOR OF BUILDING AND PROPERTY. NO TRASH, DEBRIS SHALL BE DEPOSITED UPON THE PREMISES OR ADJACENT STRUCTURES.

CASE NO: CE03101276
CASE ADDR: 2941 NW 68 ST
OWNER: RUSSO, SCARLET D
INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

- A. INSTALLATION OF KITCHEN CABINETS.
- B. INSTALLATION OF LIGHT POST AT ENTRY.
- C. INSTALLATION OF FRONT REPLACEMENT DOOR.

CODE ENFORCEMENT BOARD

CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

CASE NO: CE03110158 CASE ADDR: 3307 NW 69 CT

OWNER: ROYER, YVETTE 1/2 INT, O'HARA, HENRY INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE INTERIOR OF THE BUILDING AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS

INCLUDES, BUT IS NOT LIMITED TO:

A. INSTALLATION OF DOORS AND WINDOWS.

B. ENCLOSURE OF CARPORT.

C. INSTALLATION OF SWIMMING POOL.

FBC 104.2.11

INSTALLATION OF NEW AIR CONDITIONING WAS INSTALLED WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

FBC 104.2.4

THERE HAS BEEN MODIFICATIONS TO THE EXTERIOR PLUMBING AND DRAIN LINES WITHOUT FIRST OBTAINING THE REQUIRED PERMITS.

FBC 104.2.5

ELECTRICAL RENOVATION, RELOCATION AND NEW INSTALLATION WORK WAS DONE WITHOUT FIRST OBTAINING REQUIRED PERMITS.

CASE NO: CE03110594 CASE ADDR: 2312 NW 14 ST OWNER: ALLWEISS, HARRISON INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR PLUMBING CONNECTIONS WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

A. INSTALLATION OF EXTERIOR SEWER LINE AND WASTE CONNECTIONS

CASE NO: CE03120248 CASE ADDR: 1704 NW 8 CT

PETER, GEORGE & YVES ROSE OWNER:

INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT LIMITED TO:

- A. INSTALLATION OF DRYWALL AND FRAMING
- B. INTERIOR REMODEL

CODE ENFORCEMENT BOARD CITY COMMISSION MEETING ROOM - CITY HALL JANUARY 27, 2004

10:00 AM

CASE NO: CE03120383

CASE ADDR: 6636 NW 20 AVE
OWNER: IDEAL INDUSTRIAL PROPERTIES LTD
INSPECTOR: DOUGLAS KURTOCK

VIOLATIONS: FBC 104.1

THERE HAVE BEEN PHYSICAL ALTERATIONS AND IMPROVEMENTS TO THE PROPERTY AND EXTERIOR STRUCTURE WITHOUT FIRST OBTAINING THE REQUIRED BUILDING PERMITS. THIS INCLUDES, BUT IS NOT

LIMITED TO:

A. INSTALLATION OF INTERIOR OFFICE SPACE

B. INSTALLATION OF COMMERCIAL BAKING EQUIPMENT AND OVEN